

MR-ES	MR-JE	MR-J2S-Series	MR-J3-Series	MR-J4-Series	Japan type	Resistance [Ohm]	Power [W]		MEU type	Resistance [Ohm]	Power [W]
MR-E-10..100	MR-JE-10..100	MR-J2S-10...100	MR-J3-10...100	MR-J4-10...100	MR-RB032	40	30	<->	MR-RFH75-40	40	150
MR-E-20..100	MR-JE-10..100	MR-J2S-20...100	MR-J3-20...100	MR-J4-20...100	MR-RB12	40	100	<->	MR-RFH75-40	40	150
MR-E-70..100	MR-JE-70...100	MR-J2S-70...100	MR-J3-70...100	MR-J4-70...100	MR-RB32	40	300	<->	MR-RFH220-40	40	400
MR-E-200	MR-JE-200..300	MR-J2S-200...500	MR-J3-200...350	MR-J4-200...350	MR-RB30	13	300	<->	MR-RFH400-13	13	600
MR-E-200	MR-JE-200..300	MR-J2S-200...500	MR-J3-200...350	MR-J4-200	MR-RB50	13	500	<->	MR-RFH400-13	13	600
		MR-J2S-700	MR-J3-500...700	MR-J4-500...700	MR-RB31	6,7	300	<->	MR-RFH400-6.7	6,7	600
		MR-J2S-700	MR-J3-500...700	MR-J4-500...700	MR-RB51	6,7	500	<->	MR-RFH400-6.7	6,7	600
				MR-J4W2-22...44	MR-RB14	26	100	<->	MR-PWR-R T 600-26	26	600
				MR-J4-350 MR-J4W2-77...1010	MR-RB3N	9	300	<->	MR-PWR-R T 400-9	9	400
				MR-J4W3-222...444	MR-RB34	26	300	<->	MR-PWR-R T 600-26	26	600
		MR-J2S-60_4			MR-RB1L-4	270	100	<->	MR-PWR-R T 150-270	270	150
		MR-J2S-100_4	MR-J3-60...100_4	MR-J4-60...100_4	MR-RB3M-4	120	300	<->	MR-PWR-R T 400-120	120	400
		MR-J2S-200_4			MR-RB3H-4	80	300	<->	MR-PWR-R T 600-80	80	600
		MR-J2S-200_4			MR-RB5H-4	80	500	<->	MR-PWR-R T 600-80	80	600
		MR-J2S-350...500_4	MR-J3-200...350_4	MR-J4-200...350_4	MR-RB3G-4	47	300	<->	MR-PWR-R T 600-47	47	600
		MR-J2S-350...500_4	MR-J3-200...350_4	MR-J4-200...350_4	MR-RB5G-4	47	500	<->	MR-PWR-R T 600-47	47	600
		MR-J2S-700_4	MR-J3-500...700_4	MR-J4-500...700_4	MR-RB34-4	26	300	<->	MR-PWR-R T 600-26	26	600
		MR-J2S-700_4	MR-J3-500...700_4	MR-J4-500...700_4	MR-RB54-4	26	500	<->	MR-PWR-R T 600-26	26	600

Oliver Giertz  
 Oliver.giertz@meg.mee.com  
 Version 19.03.2014